

Figure 4-20. ARA-23 in situ gamma survey and estimated Cs-137 concentrations in the top 1 in. of soil.